Audited and admitted for Rs. 4607111=00

Passed by Cheque for Rs. 3974321=00

M. A. R. 57 (Rule 116)

Measurement Book

No. B 341717

Serial No. .....

Name of Work ..... 632790=00 From ..... To .....

Name of Contractor of nature of Agency .....

Date of commencement of work .....

by adjustment

Date	Full description, etc, of work	Number	Dimensions: Length	Breadth	Depth	Contents	Reference to last Measurement
1		3	4	5	6	7	8



Accounts Superintendent
B.B.

Executive Engineer
Begurmahalli Division

Checked
26/5/15

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರ
ಬೆಟ್ಟಹಳ್ಳ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲ
ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂ

Scanned by CamScanner

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Reference to last Measurement
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	8
I-11	Disposal of debris to the final place of disposal with all lead & lift & as direction by the engineer in charge of work. vide item no (1)					609.04 cum @ 72=71	
	Total Amount	4188983=00					
Rani. N.K. 28/5/15	SKR I DL 10% + Cess 1% OR 1%	460711=00				41 88 28 = 0	
		41882=00					
		4690876=00				4607111=00	

Certificate

(1) certified that contractor has done the work satisfactory.
(2) certified that there is no due work from contractor side
(3) certified that Contractor has removed all debris from work spot.

ಸಹಾಯಕ ಅಭಿಯಂತರರು
ಬೆಳ್ಳಹಳ್ಳಿ ಉಪವಿಭಾಗ, ಬಾಸವಹಳ್ಳಿ ಪಂ.

Scanned by CamScanner